

siegmund **work**

Maintenance products





PROTECTION AGAINST WELD SPATTER ADHESION ON THE WORK TABLE:

- Anti-Spatter spray is preferably applied with a spray bottle before welding
- The effect of Anti-Spatter works in wet as well as dried condition
- After use, welding spatters can be wiped off easily
- The product can also be used on the components that are being welded on the table




CLEANING THE WORK TABLE:

- CleanBasic is an intense water-based cleaner
- The work table should be cleaned after each welding
- CleanBasic is suitable for removing fats, oils and other impurities
- The cleaner diffuses through plastic containers, which can shrink the volume



TO MAINTAIN THE SMOOTH SURFACE OF YOUR WORK TABLE AND ACCESSORIES:

- The Oilstone is used to remove damages or welding spatters
- Ideal tool to maintain the smoothness of the table surface
- Not suitable for use on plasma nitrided tables



CLEANING OF THE HOLES OF A WORK TABLE:

- Grime in bore holes can be removed effortlessly with the brush